HONDASHOP MANUAL NEWSOUTBOARD MOTORPower EquipmentBF20A • BF25ANews No.News No.Iesue DateP/P-032August '94

SOME PARTS OF CHANGES

Applicable information	Publication No.
BF20A · BF25A	66ZV700

CHANGE LOCATIONS

The part numbers of the pin driver, 4mm and the special tool illustrations have been corrected as follows.

•Pin driver, 4mm


BEFORE MODIFICATION

07944-9350200

AFTER MODIFICATION

07744-0010300 or 07944-SA00000

Special tool illustrations



HONDA MOTOR CO., LTD. SERVICE PUBLICATIONS