



# General Instructions

## Tools

The following tools are recommended for the Take Apart procedures:

- ESD wriststrap and mat
- Flat -blade screwdriver
- Magnetized Phillips screwdriver
- Torx T8 screwdriver
- Torx T10 screwdriver
- Pliers
- Jeweler's Phillips screwdriver
- Black stick (or other nonconductive plastic or nylon tool)

**Note:** To organize the screws you remove from the assembly, use a tray with divided compartments (such as a plastic ice cube tray).

## Serial Number Location

In this computer, the product serial number is located on the base near the computer latch.